

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2023

Submitted Date:

10/09/2023

Document Number:

713600282

FIELD INSPECTION FORM

Loc ID: 324843 Inspector Name: COSTA, RYAN On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16520
Name of Operator: CHEMCO INC
Address: 6970 SOUTH HOLLY CIR STE 206
City: CENTENNIAL State: CO Zip: 80112

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Neher, Morgan		morgan@chemco-og.com	
Enforcement		dnr_cogccenforcement@state.co.us	
Neher, Gray		gh.neher@chemco-og.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213091	WELL	SI	08/02/2022	OW	061-06452	BAUGHMAN 6	RI

General Comment:

On 10/5/2023, Ryan Costa conducted a follow up of the previous inspection #713600280. The corrective actions of the previous reclamation inspection have not been performed. Operator is directed to perform corrective actions outlined on this inspection report immediately. Non-compliance with the Rules will be referred to enforcement. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	The well sign is laying on the ground not properly installed. Corrective action will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	10/05/2023

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Some of the unused supplies were removed however, there are still parts laying next to the pumpjack. There is also an unused pipe riser near the tank. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	08/09/2023

Overall Good:

Spills:

Type	Area	Volume	
Crude Oil			
Comment:	There is oil stained soils at the pumpjack, tank battery, and separator that must be cleaned up and properly disposed. It appears dirt was spread over the stained soils to cover up and hide the spill. Operator must clean up and properly dispose E&P waste. Upon further investigation with ENV staff the spill appears to be reportable under 912.b. Corrective action will remain out of compliance until completed.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Submit Form 19 within 72 hours to report the spill of impacted material and Contact ECMC EPS staff per Rule 912.b.		Date: 08/09/2023

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403554348	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278061
713600283	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278036