

FORM  
6Rev  
11/20

## State of Colorado

## Energy &amp; Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Replug By Other Operator

Document Number:

403547358

Date Received:

10/11/2023

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10633

Contact Name: Adam Conry

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Phone: (303) 883-3351

Address: 1801 CALIFORNIA STREET #2500

Fax:

City: DENVER State: CO Zip: 80202

Email: AConry@civiresources.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-005-06390-00

Well Name: GRIMM-TINIANOW

Well Number: 1

Location: QtrQtr: SWSW Section: 34 Township: 4S Range: 64W Meridian: 6

County: ARAPAHOE

Federal, Indian or State Lease Number:

Field Name: WILDCAT

Field Number: 99999

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.653795

Longitude: -104.544668

GPS Data: GPS Quality Value: 0.0 Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 08/25/1979

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

## Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
|           |           |           |                |                     |            |

Total: 0 zone(s)

## Casing History

| Casing Type | Size of Hole | Size of Casing | Grade | Wt/Ft | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Btm | Cmt Top | Status |
|-------------|--------------|----------------|-------|-------|---------------|---------------|-----------|---------|---------|--------|
| SURF        | 12+1/4       | 8+5/8          | J-55  | 24    | 0             | 206           | 150       | 206     | 0       | CALC   |
| OPEN HOLE   | 7+7/8        |                |       |       | 206           | 8330          |           |         |         |        |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

|     |      |              |      |        |      |     |            |           |              |                                     |
|-----|------|--------------|------|--------|------|-----|------------|-----------|--------------|-------------------------------------|
| Set | 70   | sks cmt from | 7566 | ft. to | 7366 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/>            |
| Set | 50   | sks cmt from | 3200 | ft. to | 3100 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/>            |
| Set | 150  | sks cmt from | 2000 | ft. to | 1675 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input checked="" type="checkbox"/> |
| Set | 1250 | sks cmt from | 1400 | ft. to | 206  | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/>            |
| Set | 25   | sks cmt from | 206  | ft. to | 0    | ft. | Plug Type: | CASING    | Plug Tagged: | <input type="checkbox"/>            |

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Surface Plug Setting Date: 09/10/2023 Cut and Cap Date: 09/27/2023 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 17

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: AXIS

Type of Cement and Additives Used: CLASS G, THIXO

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

#### Technical Detail/Comments:

- Venting health and safety precautions were taken to avoid nuisance and or hazards to the public.
  - Operator reviewed the stormwater program and implemented stormwater BMPs and erosion control measures as needed to prevent fine-grained sediment and impacted stormwater runoff from entering surface water.
  - Form 42 was submitted prior to plugging operations, Form 42 Doc # 403516338. Form 42 was submitted prior to MIRU for plugging operations, Form 42 Doc # 403516327.
  - No fluids or gas migration was present prior to cement plug to surface being set. The plug was cemented to surface with 25 sacks of cement from 206' - 0'.
  - At least 100' of cement was left in the wellbore for each plug.
  - This form 6-SRA addresses all COA's from the Form 6-NOIA.
  - As-Drilled GPS Data is attached to this form.
- Attached to this form:
1. Cement tickets are attached to this form.
  2. Operations summary is attached to this form for reference.
  3. Final P&A WBD is attached to this form.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Ashley Noonan

Title: Sr. Regulatory Analyst Date: 10/11/2023 Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 10/16/2023

**CONDITIONS OF APPROVAL, IF ANY:****COA Type****Description**

|       |  |
|-------|--|
|       |  |
| 0 COA |  |

**Attachment List****Att Doc Num****Name**

|           |                             |
|-----------|-----------------------------|
| 403547358 | FORM 6 SUBSEQUENT SUBMITTED |
| 403549733 | CEMENT JOB SUMMARY          |
| 403549741 | WELLBORE DIAGRAM            |
| 403549742 | OPERATIONS SUMMARY          |

Total Attach: 4 Files

**General Comments****User Group****Comment****Comment Date**

|  |  |                     |
|--|--|---------------------|
|  |  | Stamp Upon Approval |
|--|--|---------------------|

Total: 0 comment(s)