

Operator:

Location Name: State Antelope / F-30 Pad

Loc ID: 432809

Inspection: 709100058



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J



Exhibit K



Exhibit L



Exhibit M



Exhibit N



Exhibit O



Exhibit P



Exhibit Q



Exhibit R



Exhibit S



Exhibit T



Exhibit U



Exhibit V



Exhibit W

CA: No emergency contact number present on tank battery signage. Emergency number illegible from a distance from tanks. Install sign(s) to comply with Rule 605.(a).

CA Resolution: Operator has addressed the issue and Emergency Contact Number is now visible from a distance to comply with Rule 605.a.

CA: Tumbleweeds within the tank battery secondary containment. Comply with rule 606.c.

CA Resolution: Operator has properly addressed and cleared identified tumbleweeds to comply with Rule 606.c.

CA: Unused equipment (pipe) on site. Comply with rule 606.

CA Resolution: Operator has removed unused equipment from the location to comply with Rule 606.

CA: Trash and debris onsite. Comply with Rule 606.d.

CA Resolution: Operator has addressed and cleared/cleaned location of identified trash and debris to comply with Rule 606.d.

CA: Stained soil observed around the K-O-30HNB wellhead. Comply with Rules 609.d. and 905.e.

CA Resolution: Operator has appropriately addressed the identified stained soil around wellhead to comply with Rules 609.d. and 905.e.

CA: Stained soil observed next to the metal shed. Comply with Rules 609.d. and 905.e.

CA Resolution: Operator has appropriately addressed and cleaned the identified stained soil next to the metal shed to comply with Rules 609.d. and 905.e.

CA: Inadequate berms observed to have burrows present. Repair or install berms or other secondary containment devices per Rule 603.o.

CA Resolution: Operator has addressed berms with burrows present and has repaired berms to comply with Rule 603.o.



Exhibit A



Exhibit B



Exhibit C



Exhibit D




Exhibit E

CA: Sign not posted, and information written on wellhead is illegible at the K-O-30HNB wellhead. Install sign to comply with Rule 605.a.

CA Resolution: Operator has installed new signage at identified areas on location to comply with Rule 605.a.