

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403470926

Date Received:

07/20/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

JACKSON C MICHAEL

c.jackson@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 690203458

Inspection Date: 10/04/2022

FIR Submit Date: 10/05/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: AMOCO PRODUCTION COMPANY

Company Number: 2500

Address: P O BOX 3092 ROOM 2.554

City: HOUSTON State: TX Zip: 77253-309

### LOCATION - Location ID: 386457

Location Name: MGP ENTERPRISES "A"-634S66W Number: 9NWNE County: LAS ANIMAS

Qtrqr: NWNE Sec: 9 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.105024 Longitude: -104.780336

### FACILITY - API Number: 05-071-00 Facility ID: 217318

Facility Name: MGP ENTERPRISES A Number: 4

Qtrqr: NWNE Sec: 9 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.105024 Longitude: -104.780336

### CORRECTIVE ACTIONS:

2 ☒ CA# 164976

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 06/29/2023

Operator Comment: Correction of the erosion control and best management practices was completed according to the attached erosion control plan and well site monitoring.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

This CA is approved pending re-inspection. Ongoing monitoring and maintenance will be required.  
Operator's comment regarding completion of Rule 1004 is not approved.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The Rule 1002.f.(2) correction action for the erosion control and best management practices was completed 29 June 2023. Please see attached erosion control plan and well site monitoring report.

The Rule 1004 corrective action was previously completed and submitted 27 April 2023 in Sundry Form 403386221. Please also see fully attached fully executed waiver from the landowner.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: C. Michael Jackson

Signed: \_\_\_\_\_

Title: Legacy Wells Specialist

Date: 7/20/2023 10:38:28 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403470926	FIR RESOLUTION SUBMITTED
403470946	Erosion Control Plan
403470950	Erosion Control Monitoring
403471025	Landowner Waiver

Total Attach: 4 Files