



00553972

# COLORADO OIL & GAS CONSERVATION COMMISSION

## FIELD INSPECTION REPORT

NOV 21 1997



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <u>017 - 6021</u>		LEASE NAME: <u>MILLER #1</u>	
LOCATION: <u>SENE12155-45W</u>		OPERATOR: <u>MURFIN DRUG</u>	
DATE: <u>11-10-97</u>		INSPECTOR: <u>R. Vansickle</u>	
Insp. Type: <u>SR</u>	Insp. Status: <u>PA</u>	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/> Viol.: Y <input checked="" type="radio"/> N <input type="radio"/> NOV: Y <input type="radio"/> N <input type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	<u>ESP controller &amp; some timbers remain @ site</u>	✓
<b>Miscellaneous</b>		

**CORRECTIVE ACTION REQUIRED:** Remove equipment

Date Corrective Action Required By: 1-10-98

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.