

Weld OEM Spill Report Form

Submitted on	20 October 2023, 9:33AM
Receipt number	1424
Related form version	17

Company

Company name	Civitas Resources
Address	650 Southgate Drive
City	Windsor
State	Colorado
Zip code	80550

Contact Information

Contact person	Costin McQueen
Contact phone	720-384-6452
Contact email	cmcqueen@civiresources.com

About the Spill

Date incident occurred	10/19/2023
Was 9-1-1 called for this incident	No
Longitude	-104.646902
Latitude	40.245131
Fire department/district	Lasalle Fire
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	Aristocrat 31-10C
----------------	-------------------

Section	10
Township	3N
Range	65W
Where did the spill occur	Well head
Have you submitted a form 19	Yes
Form 19 report number	403567078

Product Spilled

Product spilled	oil, produced water, condensate
Number of barrels spilled	0
Emergency precautions taken	N/A
Extremely hazardous substance	No
Acute or chronic health risks	No
Did the spill affect or end near a waterway, irrigation ditch, or a retention pond?	No
What caused the spill/release?	Historical

Narrative

<p>Include specific incident information and mitigation actions taken to stop and clean-up the spill/release</p>	<p>During facility decommissioning activities at the Aristocrat 31-10C, high PID's were observed indicating a possible historical release. Confirmation soil samples were collected and submitted for analysis of ECMC Table 915-1. The impacted soil will be removed and hauled for disposal.</p>
<p>Acknowledgement</p>	<p>I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.</p>