


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



**Location Overview: Location is within High Priority/Density
Habitat areas. Location is approximately 27 yards from a
drainage that contributes to the Colorado River.**

Section/Township/Range: 19 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3590 Ditch needs maintenance (runs across entrance to location)

Photo # 3591 Ditch needs maintenance (runs across entrance to location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3592 Ditch needs maintenance (runs across entrance to location)



Photo # 3593 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3594 Erosion & transport of sediment off location



Photo # 3595 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3596 Erosion & transport of sediment off location



Photo # 3597 Erosion & transport of sediment off location into the interim area choking off vegetation & erosion in the interim area

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3598 Erosion & transport of sediment off location into the interim area choking off vegetation & erosion in the interim area

Photo # 3599 Erosion & transport of sediment off location into the interim area choking off vegetation & erosion in the interim area

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3600 Erosion & transport of sediment off location into the interim area choking off vegetation & erosion in the interim area



Photo # 3601 Erosion & transport of sediment off location into the interim area choking off vegetation & erosion in the interim area

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 3602 Erosion & transport of sediment off location into the interim area choking off vegetation

Photo # 3603 Erosion & transport of sediment off location into the interim area choking off vegetation