

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 19 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3660 Sediment trap needs maintenance (W/NW area of location)

Photo # 3661 Check dam needs maintenance (W/NW area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3662 Sediment trap needs maintenance (NW corner of location)

Photo # 3663 Sediment trap needs maintenance (NW corner of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3664 Sediment trap needs maintenance (NW corner of location)



Photo # 3665 Ditch needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3666 Ditch needs maintenance

Photo # 3667 Check dam needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3668 Check dam needs maintenance



Photo # 3669 Check dam needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3670 Sediment trap & drain need maintenance (SE corner of location)

Photo # 3671 Sediment trap & drain need maintenance (SE corner of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3672 Sediment trap & drain need maintenance (SE corner of location)

Photo # 3673 Sediment trap & drain need maintenance (SE corner of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3674 Erosion on slope & transport of sediment onto location (S/SE area of location)

Photo # 3675 Erosion on slope & transport of sediment onto location (S/SE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad
Location ID: 335382



Photo # 3676 Erosion on slope & transport of sediment onto location (S/SE area of location)

Photo # 3677 Erosion on slope & transport of sediment onto location (S/SE area of location)