

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403562776

Date Received:  
10/17/2023

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 88370  
Name of Operator: TIMKA RESOURCES LTD  
Address: 2077 BAYFRONT DR  
City: WINDSOR State: CO Zip: 80550

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Todd Pivonka</u>	<u>970-590-5617</u>	<u>timkaresources@hotmail.com</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 708200605  
Inspection Date: 10/05/2023 FIR Submit Date: 10/12/2023 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMKA RESOURCES LTD Company Number: 88370  
Address: 2077 BAYFRONT DR  
City: WINDSOR State: CO Zip: 80550

LOCATION - Location ID: 322914

Location Name: BOUNTY-68N57W Number: 35SESE County: \_\_\_\_\_  
Qtrqr: SESE Sec: 35 Twp: 8N Range: 57W Meridian: 6  
Latitude: 40.611750 Longitude: -103.717440

FACILITY - API Number: 05-123-00 Facility ID: 322914

Facility Name: BOUNTY-68N57W Number: 35SESE  
Qtrqr: SESE Sec: 35 Twp: 8N Range: 57W Meridian: 6  
Latitude: 40.611750 Longitude: -103.717440

**CORRECTIVE ACTIONS:**

1  CA# 184935

Corrective Action: Comply with Rule 606. Location will remain out of compliance until the corrective action has been resolved. Date: 10/05/2023

Response: CA COMPLETED Date of Completion: 10/16/2023

Operator Comment: Field Bindweed and Russian Thistle eradicated from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2  CA# 184936

Corrective Action: Comply with Rule 1002.f. The location will remain out of compliance until the corrective action has been resolved.

Date: 10/05/2023

Response: CA COMPLETED

Date of Completion: 10/16/2023

Operator Comment: Access road and location graded to fix/repair rill erosion.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Todd Pivonka

Signed:

Title: VP

Date: 10/17/2023 11:05:15 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403562776	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files