



99999999

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

MAY 2 1975

Bols State

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

D-032682

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

W. Don Quigley

3. ADDRESS OF OPERATOR

803 Phillips Petro. Bldg. Salt Lake City, Utah 84101

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

NW. SE. SEC. 11, T. 1 N., R. 102 W., 6th P.M.
1604' from S-line & 2219' from E-line

14. PERMIT NO.

68-382

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5438' grd.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., Q., R., T., OR BLK. AND SURVEY OR AREA

Sec. 11-1N-102W

12. COUNTY OR PARISH 13. STATE

Rio Blanco Colo.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-29-74

Well has quit producing and the equipment has been removed. The well has been plugged and abandoned in the following manner:

1. Cleaned out well to 1970'. Hole started caving badly and began sticking tools. Could not get below this depth and had no oil, so decided to plug well.
2. Placed a 30-sk cement plug at 1970'-1850', at bottom of hole and on top of bridge.
3. Placed a 24-sk cement plug at 325' to 225', across bottom of surface casing.
4. Placed well marker and ten-sk cement plug in the top of the surface casing.
5. Cleaned and levelled location.

DVR	
FJP	✓
MHM	✓
JAW	✓
JJD	✓
GCH	✓
CGM	

EXHAUSTED
OIL WELL



00043963

18. I hereby certify that the foregoing is true and correct

SIGNED

W. Don Quigley

TITLE

Cons. Geol.

DATE

Apr. 30, 1975

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DIRECTOR

DATE

OCT 7 1975

CONDITIONS OF APPROVAL, IF ANY:

X