



00046726

OIL AND GAS CONSERVATION COMMISSION
OF THE STATE OF COLORADO
Room 312, State Services Bldg.
1525 Sherman Street
Denver, Colorado 80203

H & M Drilling Company

September 12, 1966

Box 543

Rangely, Colorado

Gentlemen:

We have not received reports, as checked below, for the following well:

2 Gov. SESE 10-1N-102 W Rangely, Rio Blanco

2 well was lost and plugged and rig skidded to drill 2X

COMMENTS: Note: New well will be numbered 2-X.

- ☐ Form 1 Designation of Agent
- ☐ Form 2 Application for Permit to Drill, Deepen, or Plug Back
- ☐ Form 3 Bonding Requirements
- ☒ Form 4 Sundry Notices and Reports on Wells
send in notice stating # 2 plugged and skidded only verbal on file.
- ☐ Form 5 Well Completion or Recompletion Report and Log
- ☐ Form 10 Certificate of Clearance
- ☐ Others:

Please submit the above requested reports to this office as soon as possible.

OIL AND GAS CONSERVATION COMMISSION

D. V. Rogers

D. V. Rogers, Director