

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403520374

Date Received:

09/05/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

johnston, tyson

geops@oxbow.com

Grey, Daniel

tyson.johnston@oxbow.com

daniel.gray@usda.gov

wtoews@blm.gov

dnr_cogccenforcement@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205094

Inspection Date: 07/10/2023

FIR Submit Date: 07/12/2023

FIR Status: _____

Inspected Operator Information:

Company Name: GUNNISON ENERGY LLC

Company Number: 10515

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324464

Location Name: FEDERAL-610S90W Number: 30SWSE County: _____

Qtrqtr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.156037 Longitude: -107.477714

FACILITY - API Number: 05-051- -00 Facility ID: 324464

Facility Name: FEDERAL-610S90W Number: 30SWSE

Qtrqtr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.156037 Longitude: -107.477714

CORRECTIVE ACTIONS:

1 ☒ CA# 175223

Corrective Action: Comply with 606 Rules. The "Date of Discovery" is being provided as the corrective action date. Location will remain out of compliance until corrective action has been resolved.

Date: 07/10/2023

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator
Comment:

Loose materials were picked up immediately. However, it should be noted that Pipe, Equipment and other remanence referenced in photos 2 and 3 are part of the Ragged Mountain Compressor Station decommissioning (Location ID 120678) that is ongoing. There are three elements residing on the same footprint: 1) The Ragged Mountain Compressor Station (Loc ID. 120678); 2) the Ragged Mountain Pipeline (GELLC Operated) tie in and metering to Bull Mountain Pipeline (SG Interests operated) which will remain so long as gas is produced by GELLC in this field; and 3) the Federal 30-4 well and associated facilities. I photo indicating the locations of the associated facilities on this location attached for your convenience.

Gunnison Energy respectfully requests that items are written up in accordance with the locations/facilities such items directly belong to so the record is more clearly delineated.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2  CA# 175224

Corrective Action: Comply with NOAV #403040539 Abatement or Corrective Action requirements.

Date: 06/05/2022

Response: CA COMPLETED

Date of Completion: 07/12/2023

Operator
Comment:

NOAV #403040539 is in process. This FIR should not remain open due to another FIRs pending process.

COGCC Decision: **Not Approved**

COGCC
Representative:

OGCC Decision "Not Approved".

Operator response of "Corrective Action Complete" is a notification to the State that the corrective action has been addressed in its entirety. Based on operator comments corrective action does not appear to have been completed. Additionally, NOAV #403040539 required Operator to conduct and submit (attached to a Form 4) a detailed assessment of the disturbed areas attached to NW Reclamation Specialist Trujillo by 6/5/2022. To date no assessment has been submitted via a Form 4 to NW Reclamation Specialist Trujillo; Operator has failed to comply with both the FIR and NOAV corrective actions, therefore this CA and date will remain applicable.

3  CA# 175225

Corrective Action: Comply with Rule 1002.f. The "Date of Discovery" is being provided as the corrective action date. The Location will remain out of compliance until corrective action has been resolved.

Date: 07/10/2023

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator
Comment:

Culvert was cleaned out and soil sampling hole was filled for safety. Sampling locations have GPS so they can be reopened if necessary.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyson Johnston

Signed: _____

Title: Vice President

Date: 9/5/2023 2:22:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403520374	FIR RESOLUTION SUBMITTED
403520387	Location equipment delineation

Total Attach: 2 Files