

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2023

Submitted Date:

10/24/2023

Document Number:

699107670

FIELD INSPECTION FORMLoc ID 328437 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
328437	LOCATION	AC			-	Guttersen State D28-18D Pad	SI

General Comment:[This is an inspection on the tank battery](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris "tumble weeds" around the location needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	11/03/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Panel fence fell over and needs to be fixed. See attached photo.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	11/03/2023
Type	SEPARATOR		
Comment:	Panel fence fell over and needs to be fixed. See attached photo.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	11/03/2023

Equipment:			corrective date
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		40.203500,-104.559500
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 328437 Type: LOCATION API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI Tank Battery

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary
 On Monday 10/23/23 at approximately 1002hrs I, Inspector Adam Burns,
 Conducted an on-site inspection at Guttarsen State D28-18D Tank Battery of Chevron.
 Location ID #328437 in Weld County, Colorado.
 During this inspection the following possible compliance issues were observed:
 Debris "tumble weeds" around the location needs to be removed for good housekeeping.
 Comply with Rule 606. With a Corrective Action date of 11/3/23
 Panel fence fell over and needs to be fixed. Comply with the fencing requirements per the
 1002a rules. With a Corrective Action date of 11/3/23
 A follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with ECMC rules.
 This is a summary of the inspection report.

burnsa

10/24/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403571008	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6296371
699107671	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6296354