

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403574107

Date Received:

10/26/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 5 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Laramie

cogccnotifications@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205152

Inspection Date: 08/07/2023

FIR Submit Date: 08/10/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 335647

Location Name: Cascade Creek (CC) Number: 0603-23-32 County: _____

Qtrqr: NESW Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.548442 Longitude: -108.210463

FACILITY - API Number: 05-045- -00 Facility ID: 335647

Facility Name: Cascade Creek (CC) Number: 0603-23-32

Qtrqr: NESW Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.548442 Longitude: -108.210463

CORRECTIVE ACTIONS:

4 ☒ CA# 178060

Corrective Action: Comply with Rule 1002.f and install or repair required stormwater and erosion control measures to stabilize slopes.

Date: 08/04/2023

Response: CA COMPLETED

Date of Completion: 09/29/2023

Operator Comment: Slopes have been stabilized

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Based on the photo documentation provided, it is unclear if control measures to stabilize the soils have been implemented; a field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
-----------------------	---

OPERATOR COMMENT AND SUBMITTAL

Comment: This Inspection number is incorrectly attached to the 603-23-32 location. The inspection is for the 697-03-07. The remaining FIRRS have been filed under Doc# 403641184 and are not showing up as completed on this FIR.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: _____

Title: Regulatory Specialist

Date: 10/26/2023 1:57:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403574107	FIR RESOLUTION SUBMITTED
403574119	CA Photos

Total Attach: 2 Files