

DIFFERENT FOOTAGE FROM SOUTH LINE
(1225 VS 1300), BUT TWIN ARROW
SAID THEY DID HAVE A RESURVEY, SO I
BELIEVE THIS IS THE SAME WELL.




00063643

[Signature]

JJK

Katy - NESWSE, NOT ON
Call about this PLAT

well - OK? 
when drilled, etc.

H. GeBauer
GeBauer

Twin Arrow bought lease from GeBauer.
BLM found well and made Twin Arrow
plug the well. Don't have A permit #.

August 29, 1968 depth 4170
hole problems

4-19-66 - permit issued

maybe produced 30 Bbls on test
will send what papers they have