



00063646

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE (Other instructions on reverse side)

RECEIVED

NOV 29 1968 Form approved. Budget Bureau No. 42-R1424. 3. LEASE DESIGNATION AND SERIAL NO. Denver 033804(b) 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [] OTHER [] 2. NAME OF OPERATOR L. A. Gebauer dba LuBauer Petroleum Company 3. ADDRESS OF OPERATOR 414 C A Johnson Bldg 509 17th St. Denver, Colorado 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1225 feet from south line; 1425 feet from west line. 7. UNIT AGREEMENT NAME none 8. FARM OR LEASE NAME 9. WELL NO. 50 10. FIELD AND POOL, OR WILDCAT Rangely Mancos Shale 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 11 IN 102W 6th P.M. SESW 12. COUNTY OR PARISH Rio Blanco 13. STATE Colorado 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5423' Gr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF [] PULL OR ALTER CASING [] FRACTURE TREAT [] MULTIPLE COMPLETE [] SHOOT OR ACIDIZE [] ABANDON* [] REPAIR WELL [] CHANGE PLANS [] (Other) Clean out & test [X] SUBSEQUENT REPORT OF: WATER SHUT-OFF [] REPAIRING WELL [] FRACTURE TREATMENT [] ALTERING CASING [] SHOOTING OR ACIDIZING [] ABANDONMENT* [] (Other) [] (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was drilled to a depth of 4174' and produced 30 barrels per day. In cleaning out a bailer was stuck in hole and have been waiting for a special tool to remove bailer. Needs bailer taken from bottom of hole and cleaned out and put on production.

RECEIVED DEPT OF OIL & GAS OPERATIONS AUG 30 1968 U.S. GEOLOGICAL SURVEY COLORADO

18. I hereby certify that the foregoing is true and correct SIGNED [Signature] TITLE Owner DATE 8/29/68

(This space for Federal or State office use) APPROVED BY [Signature] TITLE DATE

APPROVED SEP 3 1968 RUDOLPH C. BAIER, JR. ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side