

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2023

Submitted Date:

11/07/2023

Document Number:

712700835

FIELD INSPECTION FORM

Loc ID 313563 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10506
Name of Operator: SEELEY OIL COMPANY LLC
Address: PO BOX 1058
City: CORTEZ State: CO Zip: 81321

Findings:

- 16 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Seeley, Nathaniel	(970) 565-2136	nathaniel@seeleyoil.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224487	WELL	SI	12/01/2021	OW	083-06552	CUTTHROAT 9	SI

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Long access across private land. Locked gate, Seeley combo. Dirt surfaced.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Lube oil label not legible.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Warning signs on pumpjack. Warning signs on separator.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Location recently dragged.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Lube oil container.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	2-3" line from wellhead to separator. 1-1" line from separator to prime mover.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas motor		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Entire containment berm is weathered and eroded. See photos #7-#8.		
Corrective Action:	Repair or install berms or other secondary containment devices.	Date:	12/07/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224487 Type: WELL API Number: 083-06552 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 11/29/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Compaction				
Drains	Pass	Ditches	Pass			
Compaction	Pass					
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Fail	Lube oil container has no spill prevention.

Comment: Lube oil container with no spill prevention.
No visible erosion or sediment migration observed during inspection.

Corrective Action: Implement spill prevention per Rule 1002.f.(2)B.

Date: 11/22/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700841	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313297