

Inspection Photos

11/06/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850
/ NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)

Inspection Doc: 696205408

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 1: Photos 1-2 taken from the east end of the working pad surface. Photos provide an overview of the Location from south, southwest northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



November 6, 2023



November 6, 2023

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 3: Photos examples showing berm constructed along the perimeter of the WPS; erosion logs implemented along the Locations disturbance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 4: Photos examples showing slopes of the Location are bare, lack stabilization and are at risk to wind and water erosion; stormwater and erosion control measures inadequate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 5: Photos show examples of trash debris observed along the slopes and berm of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 6: Photos taken from the Location entrance. “Drive Over Berm” to manage runoff has not been constructed per Operator’s documents attached to the Form 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 7: Photos taken from the access road. Previous inspection observed that stormwater runoff from the Location has resulted in degradation the Location's entrance and access road. The Location entrance has been re-constructed, however erosion degradation along the access road remains apparent.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850 / NONSUCH NATURAL GAS INC #10163

Location ID: 322524 (TEP), 453726 (Nonsuch)



Photo 9: Photo shows Nonsuch equipment associated with the CSOC 697-14 Tank Battery Facility remains on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources