

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403590481

Date Received:
11/09/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701900958

Inspection Date: 07/01/2023

FIR Submit Date: 07/18/2023

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 327364

Location Name: ANNIE-65N65W Number: 9NENW County: _____

Qtrqtr: NENW Sec: 9 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.419385 Longitude: -104.670279

FACILITY - API Number: 05-123-00 Facility ID: 327364

Facility Name: ANNIE-65N65W Number: 9NENW

Qtrqtr: NENW Sec: 9 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.419385 Longitude: -104.670279

CORRECTIVE ACTIONS:

1 CA# 175938

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 07/01/2023

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/06/2023

Operator Comment: After field verification, the former well head is located within the same vegetation as the production facility. It appears from the photo and supplied aerial image, the inspector marked former well location about 30 yards south of the actual well and outside PDC's disturbance. The disturbance the inspection may identify as PDC's was from the associated mine.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: After field verification, the former well head is located within the same vegetation as the production facility. It appears from the photo and supplied aerial image, the inspector marked former well location about 30 yards south of the actual well and outside PDC's disturbance. The disturbance the inspection may identify as PDC's was from the associated mine.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

Title: H&S Specialist-Operations

Date: 11/9/2023 8:03:11 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403590486	Annie Aerial
403590487	Annie Aerial 2

Total Attach: 2 Files