

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2023

Submitted Date:

11/03/2023

Document Number:

694500605

**FIELD INSPECTION FORM**Loc ID 446527 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Blohm, Justin	520-820-2380	justin.blohm@fulcrumeo.com	

**General Comment:**

ON 11/2/23 C ECMC staff inspected the Spill at the Pintail location. At the time of inspection, weather was dry, overcast and 45 degrees. Crews were inside the Tank Battery secondary containment removing fluid with a Vac truck. Nearly all of the surface of the engineered secondary containment was observed as coated with spilled fluid. No oil was observed weeping or spilled outside of secondary containment. 2 totes were observed near a fired line heater on the south east side of location. The totes were labeled as Ethylene Glycol but had a dark fluid in them. Corrective Actions: Continue with clean up and documentation on the Form 19. Remove or Properly store fluid in chemical totes, RULE 606, 605.h.(3). See attached Photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	near fired heater, on south east side of location there were some stored totes. The totes were labeled as Ethylene Glycol, it was obvious that there is a fluid other than Glycol contained in these totes.		
Corrective Action:	Remove totes and dispose of fluid appropriately.		Date: 11/17/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403583961	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6309243">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6309243</a>
694500606	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6309237">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6309237</a>