

McKeen32-6-15,1

Document number 712700844

Date completed 11/14/2023

Removed stained soil from around beam unit

