

Interim Reclamation and Stormwater Inspection

Date: 11/08/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 423036

Inspection Document #: 708200696

Morgan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Wickstrom 7-11-5-60
Location ID: 423036



Photo 1. Undesirable vegetation (e.g. russian thistle, kochia, crested wheatgrass) observed near the entrance to the location. Additional reclamation activities are required in order to comply with Rule 1003.

Inspection Photos

Location Name: Wickstrom 7-11-5-60

Location ID: 423036



Photo 2. Continued from Photo 1; eastern portion of the location within the interim areas.



Photo 3. Close up of crested wheatgrass and kochia.

Inspection Photos

Location Name: Wickstrom 7-11-5-60

Location ID: 423036



Photo 4. Eastern interim areas; see comments in Photo 1.



Photo 5. Sediment trap on the east side of the production areas; maintenance is required as it is beginning to fill with sediment.



Photo 6. Debris and animal burrows observed on the eastern portion.



Photo 7. Continued from Photo 6; unstabilized soils originating from animal burrows.

Inspection Photos
Location Name: Wickstrom 7-11-5-60
Location ID: 423036



Photo 8. Southern interim areas; see comments in Photo 1.

Inspection Photos
Location Name: Wickstrom 7-11-5-60
Location ID: 423036




Photo 9 & 10. Stained soil at wellhead and just north of wellhead within production areas.

Inspection Photos

Location Name: Wickstrom 7-11-5-60

Location ID: 423036



Photo 11. Undesirable vegetation (e.g. russian thistle and crested wheatgrass) observed throughout the former drilling pit. Additional reclamation activities are required.