

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2023

Submitted Date:

11/17/2023

Document Number:

702502145

FIELD INSPECTION FORM

Loc ID 315986 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 10775
Name of Operator: KT RESOURCES LLC
Address: 3381 WESTBROOK LANE
City: HIGHLANDS State: CO Zip: 80129

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Engineering, ECMC		dnr_cogccengineering@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231858	WELL	SI	09/01/2016	GW	103-09529	FEDERAL 33-4-B	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Wednesday, 11/15/2023, Inspector Kirby Burchett, conducted a routine field inspection at KT Resources LLC on the Federal 33-4-B well, Location #315986, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Bradenhead inaccessible.
 2. No visible display of gas meter calibration.
 3. Last produced – August 2016. No record of MIT.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(800) 288-0560 or 911	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration not visibly displayed.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: 11/26/2023
Type: Other	# 1		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow Bradenhead visual inspection.		Date: 11/16/2023
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 231858 Type: WELL API Number: 103-09529 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Produced - August 2016
Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanical intervention) within 2 years per Rule 319.b.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. Date: 12/16/2023

BradenHead

Date of Last Brhd Test: 07/11/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: ECMC database indicates Bradenhead Test performed on 7/11/23. 12/16/2023

Corrective Action: Verify Form 17 as Bradenhead is not visible or accessible at time of inspection. Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	434294	400314908	
	434294	400314908	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702502146	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6326860