



00053472

OIL AND GAS CONSERVATION COMMISSION

OF THE
STATE OF COLORADO
STEVE McNICHOLS, GOVERNOR
ROOM 312, STATE SERVICES BLDG.
1525 SHERMAN ST.
DENVER 3, COLORADO



OIL & GAS
CONSERVATION COMMISSION

WARWICK M. DOWNING
CHAIRMAN
H. C. BRETSCHNEIDER
VICE-CHAIRMAN
W. A. DILLON
HARVEY H. HOUSTON
CHARLES D. CONRADO
A. J. JERSIN
DIRECTOR

May 24, 1960

United States Development Corporation
817 Newhouse Bldg.
Salt Lake City, Utah

Attention: Mr. George B. Anderson, President

Gentlemen:

Returned herewith please find a Notice of Intention to Drill your Robinson Ranch Banker #1 well, Lot 10, Section 12, Township 1, Range 103, Rio Blanco County. ✓


Before approval can be obtained to drill a well, we must have a designation of agent and a bond for proper plugging.

Also, before returning this intention to drill, please complete the description of township and range as to whether the township is north or south, and range east or west.

Enclosed is a copy of our Rules and Regulations, and a supply of forms which you will need.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION



A. J. Jersin, Director

AJJ:cm

United States
~~XXXXXXXXXXXX~~
~~XXXXXXXXXXXX~~ *Development Corp.*

~~XXXXXXXXXXXX~~
434 South Main

Phone Elgin 5-9761

Salt Lake City, Utah

17 East Oakland Ave

Oil and Gas Conservation Commission
of the state of Colorado

Dear Sirs:

In regards to your request as to the status of the oil well we are drilling in cole, we are very sorry as we have not answered your request before . but this was an oversite in are office,

This well was drilled to a depth of about 17 hundred feet and 5 $\frac{1}{2}$ inch casing was set to 15 Hundred feet, we encountered water all the way, that ran us in to much more money than we expected on this well, we have suspended drilling for the present, but we feel we will have the money approated to complete this well in Jan. or Feb.

We hope this will be a answer to your request, if there is any additional papers you would like us to fill out we will be glad to do so.

Thanking you in advance

Yours Truly

UNITED STATES DEVELOPMENT CORP



tta



✓

11/9/64

Checked this well on
11/5/64, well has slight
gas bubble at surface,
coming through a pool
of water. Hole appears
to have a barrel over
it and is not
properly plugged.

Jim & Hack