

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403602235

Date Received:  
11/21/2023

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 4 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Michael Cugnetti

7208456901

mcugnetti@verdadresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708200265

Inspection Date: 05/17/2023

FIR Submit Date: 05/23/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 466345

Location Name: Boydston Number: 3535 County: \_\_\_\_\_

Qtrqr: NWN Sec: 35 Twp: 9N Range: 60W Meridian: 6  
W

Latitude: 40.712886 Longitude: -104.067521

#### FACILITY - API Number: 05-123-00 Facility ID: 466345

Facility Name: Boydston Number: 3535

Qtrqr: NWN Sec: 35 Twp: 9N Range: 60W Meridian: 6  
W

Latitude: 40.712886 Longitude: -104.067521

### CORRECTIVE ACTIONS:

3 CA# 171318

Corrective Action: Comply with Rule 1002.b. Operator shall report missing topsoil quantities and use, and import Date topsoil of equal or greater agronomic properties to replace the deficit. Operator shall submit soil analytical data on the imported topsoil, and from adjacent reference area, no later than 1 month before importation, via Form 4 Sundry. Operator should use the COGCC Topsoil Protection Plan guidance for agronomic properties and analyte testing (page 4) and compare those results with a topsoil assessment for reference areas to ensure equivalent topsoil is being imported. Corrective action date is the date the location was observed out of compliance.

Date: 03/31/2023

Response: CA COMPLETED

Date of Completion: 08/11/2023

Operator Comment: The approximately 60 cubic yards of topsoil that was erroneously removed from the topsoil pile for use as fill onsite and to build stormwater BMPs, has been replaced. Form 4 sundry with the imported topsoil analysis was submitted on doc#403430656. See the attached photo documentation of corrective action.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed: \_\_\_\_\_

Title: Director of EHS&R

Date: 11/21/2023 11:18:35 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403602236	corrective action photo documentation
403602237	corrective action photo documentation
403602238	corrective action photo documentation
403602239	corrective action photo documentation
403602240	corrective action photo documentation
403602241	corrective action documentation

Total Attach: 6 Files