

Location

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Rule 606: Unnecessary / unused equipment.		
Corrective Action:	Within the designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 12/15/2023. See attached photo #1, 2, 3, 4 & 5.	Date:	12/15/2023
Type	WEEDS		
Comment:	Rule 606: Weeds, & unnecessary / unused equipment.		
Corrective Action:	Within the designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 12/15/2023. See attached photo #1, 2, 3, 4 & 5.	Date:	12/15/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					
Type: Bradenhead	# 1				
Comment:					
Corrective Action:					
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:					
Type: Horizontal Heated Separator	# 1				
Comment:		Rule 906: Stained soil in separator cabinet..			
Corrective Action:		Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/15/2023 to remove stained soil. See attached photo #6, 7 & 8.			12/15/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.992558,-104.527699
Comment:	_____				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		

Comment:	603.o.(3) Secondary containment.
----------	----------------------------------

Corrective Action:	Date:
Secondary containment is not sufficiently impervious to contain spilled or released materials. Corrective Action Date 12/15/2023 to remove stained soil. See attached photo #4.	12/15/2023

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

Wells Served By Facilities Above

API Number
001-08190

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202785 Type: WELL API Number: 001-08190 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/26/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appeared to be plumber to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday November 7th, 2023 at approximately 14:53pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: KP KAUFMANN Location name: RANDALL_22-2 API # 001-08190 Location ID #: 320134 County: Adams While there, I observed a Shut in well. During this inspection the following possible compliance issues were observed: Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within the designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 12/15/2023. See attached photo #1, 2, 3 & 5. Rule 906: Stained soil in separator cabinet. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 12/15/2023 to remove stained soil. See attached photo #6, 7 & 8. 603.o.(3) Secondary containment is not sufficiently impervious to contain spilled or released materials. Corrective Action Date 12/15/2023 to remove stained soil. See attached photo #4. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	11/14/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403596849	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6324256
700901745	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6323190