

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Anschutz-Williams 5-61-27 SWSW

Loc ID: 452726

Inspection: 696305384



Exhibit A



Exhibit B

CA: Condensate Vault West of Separators is buried by Sand, Labels no longer visible. Condensate Vault at NW Corner of Tank Berm missing Capacity Label. Install sign to comply with Rule 605.h.

CA Resolution: Identified Condensate Vaults have been appropriately addressed by the Operator to ensure that the proper signage is up to date and visible to comply with Rule 605.h.



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Locate Flags on location no longer valid. Comply with Rule 606.

CA Resolution: Operator has removed identified locate flags on location to comply with Rule 606.

CA: Tumbleweed Debris at Gas Meter Rack, North end of Location and in and around Tank Berm; Comply with Rule 606.

CA Resolution: The Operator has addressed and cleared identified tumbleweed debris to comply with Rule 606.



Exhibit A



Exhibit B

CA: South 2 Separators are open to Atmosphere. Appear to be down for Maintenance Install Temporary or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

CA Resolution: Operator has installed material to close open separators to prevent unauthorized discharge to comply with Rule 902.b.