

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2023

Submitted Date:

11/29/2023

Document Number:

710500137

## FIELD INSPECTION FORM

 Loc ID 484359 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 10797  
 Name of Operator: DESERT EAGLE OPERATING LLC  
 Address: 17101 PRESTON RD SUITE 105  
 City: DALLAS State: TX Zip: 75248
**Findings:**

- 10 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Bulf, Cathy		cathybulf@gmail.com	<a href="#">Desert Eagle Operating llc</a>
Butler, Brad	972-345-9195	butleroil@yahoo.com	<a href="#">Desert Eagle Operating llc</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484359	LOCATION	AC			-	Red Rocks 35-08	EI
484676	WELL	PR	09/29/2023	OW	071-09930	Red Rocks 35-08	EI

**General Comment:**

This is a follow-up Environmental Inspection for previous Environmental Inspection Document #710500010 for the Red Rocks 35-08 Location ID 4843359 Active well location Located in Las Animas County Colorado.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	There is a pile of trees stored on location.		
Corrective Action:	Comply with Rule 606	Date:	12/15/2023

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 484359 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 484676 Type: WELL API Number: 071-09930 Status: PR Insp. Status: EI

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
	Piles	Inadequate	37.471670	-103.539550
Comment	There is a pile of unknown material adjacent to drill cuttings. Material appears to be scrapings from the location, which were originally impacted by drill cuttings material. The material should be managed in compliance with Rule 905 for E&P Waste Management			
Corrective Action	Comply with Rule 905.			Date: 12/15/2023
Drill Cuttings	Piles	Inadequate	37.471000	-104.539000
Comment	Drill cuttings are not properly stored on location. Operator shall assure liner material is not permeable. Berm Material surrounding Drill Cuttings looks to be made up of Drill Cuttings material.  Additionally, it appears the drill cuttings pile has been reduced in size since previous inspection. If the cuttings have been transported offsite, records will need to be provided to EPS Staff per Rule 905.b(3).			
Corrective Action	Magange and store Drill Cuttings in compliance with Rule 905			Date: 08/15/2023

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

**Emission Control Burner (ECB):**

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**COGCC Comments**

Comment	User	Date
ECMC is requesting documentation showing the liner material used to store drill cutting is impermeable, Operator shall provide information for liner material by 12/15/2023	sanchezcc	11/29/2023
Original CA for Unused Equipment has been resolved	sanchezcc	11/29/2023
Original CA for Vehicle Rutting has been resolved	sanchezcc	11/29/2023
Drill cuttings are not properly stored on location. Operator shall assure liner material is not permeable. Berm Material surrounding Drill Cuttings looks to be made up of Drill Cuttings material.  Additionally, it appears the drill cuttings pile has been reduced in size since previous inspection. If the cuttings have been transported offsite, records will need to be provided to EPS Staff per Rule 905.b(3).	sanchezcc	11/29/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500138	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338459">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6338459</a>