

2/21/73

Watch this well
carefully for proper
cementing, plugging,
casing, etc. "Meeker
Home" is a few miles
to the west, bad water,
hydrostatic flows, etc.

Qm



00038215