



JUL 1 - 1996

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY

| FOR OFFICE USE ONLY | | | |
|---------------------|----|----|----|
| ET | FE | UC | SE |

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir
Use "APPLICATION FOR PERMIT - " for such proposals.)

| | | | |
|--|-------------|------------------------|---|
| 1. <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> COALBEAD METHANE <input type="checkbox"/> INJECTION WELL <input type="checkbox"/> OTHER | | | 5. FEDERAL INDIAN OR STATE LEASE NO. |
| 2. NAME OF OPERATOR Union Pacific Resources Company | | | 6. PERMIT NO. |
| 3. ADDRESS OF OPERATOR P.O. Box 7 MS 3006 | | | 7. API NO 05-123-0842800 |
| CITY Fort Worth, | STATE TX | ZIP CODE 76101-0007 | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 12 below) At Surface At proposed prod. zone | | | |
| 12. COUNTY Weld | | | 8. WELL NAME Schwab |
| | | | 9. WELL NUMBER 1-32-13 |
| | | | 10. FIELD OR WILDCAT Spindle |
| | | | 11. QTR., QTR., SEC., T.R., AND MERIDIAN SWNE S13 T1N R68W |

Check Appropriate Box to Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER _____

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
- ABANDONED LOCATION (WELL NEVER DRILLED SITE MUST BE RESTORED WITHIN 6 MONTH)
- REPAIRED WELL
- OTHER _____

*Use Form 5 - Well completion or Recompletion Report and Log for subsequent report of Multiple/Commingled Completions and Recompletions

13C. NOTIFICATION OF:

- SHUT-IN TEMPORARILY ABANDONED
Date _____
(required every 6 months)
- PRODUCTION RESUMED
Date _____
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATION ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent.

15. DATE OF WORK 6-17-96

Set CIBP at 4750'
Cap with 2 sacks of cement
Perf well at 300'
Injection rate 2 bpm at 300 psi
Pump 40 sacks of cement in to well
Dump 25 sack surface plug
cut off well head
Weld on palte
Backfill hole

61339

EXHAUSTED

EXHAUSTED OIL WELL

16. I hereby certify that the foregoing is true and correct

SIGNED Cami Cho TELEPHONE NO. (817) 877-6530

NAME (PRINT) Cami Cho TITLE Regulatory Analyst DATE 6-28-96

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE 7/5/96

H & R WELL SERVICES, INC.
17509 ROAD 14
FORT MORGAN, COLORADO 80701

(303) 867-2730 • (303) 654-1600


TO Union Pacific Resources Co.
Brighton, Colorado

| | | | |
|-------------------------|--|------------|----|
| DATE 6-17-96 | | JOB NO. | |
| PROJECT Spindle P&A | | | |
| LOCATION Schwab 1-32-13 | | | |
| CONTRACTOR | | OWNER | |
| WEATHER | | TEMP. ° at | AM |
| | | ° at | PM |
| PRESENT AT SITE | | | |
| | | | |
| | | | |

THE FOLLOWING WAS NOTED:

- Set CIBP at 4750'
- Cap with 2 sacks of cement
- Perf well at 300'
- Injection rate 2 bpm at 300 psi
- Pump 40 sacks of cement into well
- Dump 25 sack surface plug
- Cut off well head
- Weld on plate
- Backfill hole

Harlan Hodge, P&A Supervisor



COPIES TO _____

FIELD REPORT

SIGNED _____