

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403606348

Date Received:
12/05/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10814

Name of Operator: MDS ENERGY DEVELOPMENT LLC

Address: 409 BUTLER RD SUITE A

City: KITTANNING State: PA Zip: 16201

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Heibel, Krystal

krystal.heibel@state.co.us

SAADEH, RICHARD

richard.saadeh@mdsed.com

Jim Jacobsen

jim.jacobsen@iptwell.com

Arthur, Denise

denise.arthur@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200700

Inspection Date: 11/14/2023

FIR Submit Date: 11/15/2023

FIR Status: _____

Inspected Operator Information:

Company Name: MDS ENERGY DEVELOPMENT LLC

Company Number: 10814

Address: 409 BUTLER RD SUITE A

City: KITTANNING State: PA Zip: 16201

LOCATION - Location ID: 471039

Location Name: Castor 7-59

Number: 10

County: _____

Qtrqr: SWSE

Sec: 10

Twp: 7N

Range: 59W

Meridian: 6

Latitude: 40.583600

Longitude: -103.963208

FACILITY - API Number: 05-123-

-00

Facility ID: 471039

Facility Name: Castor 7-59

Number: 10

Qtrqr: SWSE

Sec: 10

Twp: 7N

Range: 59W

Meridian: 6

Latitude: 40.583600

Longitude: -103.963208

CORRECTIVE ACTIONS:

1 CA# 188207

Corrective Action: Report spill or release of E&P waste or produced fluids. Remove free fluids and contact ECMC EPS staff per Rule 912.b. 24 hours to remove free fluids. 24 hours for notification to area EPS Staff (Krystal.Heibel@state.co.us) and 72 hours for Initial Form 19 Report.

Date: 11/16/2023

Response: CA COMPLETED

Date of Completion: 11/17/2023

Operator Comment: Form 19 (Doc. number 403601177) was submitted on 11/17/2023. The spill was entirely contained within the secondary containment liner, so no soil or groundwater remediation was necessary. The spill has been fully cleaned up and complies with Table 915-1.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Regarding the corrective action #2, MDS has submitted 2 soil samples to Weld County Labs in order to get an approved soil location to finalize that corrective action. The sample were taken from:
The M&M sample location was from:

25490 WCR 58
Greeley, CO 80631

The gravel pit address is:
Burnco Pit
12210 WCR 14 ½
Fort Lupton, CO 80621

The lab is:
Weld Laboratories
1527 1st Avenue
Greeley, CO 80631

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Andrea Gross

Signed: _____

Title: Permit Agent

Date: 12/5/2023 1:19:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files