

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2023

Submitted Date:

11/29/2023

Document Number:

709100162

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
467672 _____ Heibel, Krystal _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
7 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Claxton, Bill	(303) 785-7006	bill@strachanexploration.com	All Inspections
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	
Strachan, Steven	(303) 785-7006	sms@strachanexploration.com	All Inspections
Kyle Waggoner		kyle.waggoner@state.co.us	
Greg Deranleau		greg.deranleau@state.co.us	

General Comment:

On November 7, 2023, ECMC Environmental Unit Staff Krystal Heibel and Kyle Waggoner inspected the Federal Pelican location (Location ID: 467672).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type BATTERY

Comment: Signs information inaccurate at battery. Previous operator's name is on signage.

Corrective Action: Install accurate sign to comply with Rule 605.e.

Date: 12/29/2023

Emergency Contact Number:

Comment: No emergency contact number listed visibly from tanks.

Corrective Action: Install sign to comply with Rule 605.a.

Date: 12/29/2023

Good Housekeeping:

Type WEEDS

Comment: Tumbleweeds within tank battery containment

Corrective Action: Comply with Rule 606.

Date: 12/06/2023

Overall Good:

Spills:

Type Area Volume

Crude Oil Tank <= 1 bbl

Comment: Impacted soil observed near tank battery and within metal shed near treater.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 12/29/2023

In Containment: Yes

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Other # 1

Comment: Unpermitted pit on location.

Corrective Action: Comply with rule 909.a.(1). Submit an eForm 15 Pit Permit Report to update ECMC records with current information and demonstrate compliance with Rules 908, 909, and 910, specifically Rule 909.b. Include Produced Water Quality Analyses data required by Rule 909.j. as an attachment to the Form 15.

Date: 01/01/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms


Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	Secondary containment is inadequate to contain 150% of the volume of the largest tank. Large burrows observed in berms.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	12/29/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment: Wildlife protections devices not adequate.

Corrective Action Install or repair wildlife protection equipment.

Date: 12/29/2023

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<u>Operator shall review Form 44 data for completeness and accuracy. Operator shall provide an updated Form 44 for off-location flowlines associated with this facility to the Flowline Integrity Unit no later than January 1, 2024.</u>	heibelk	11/29/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403609305	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6337617
709100163	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6337587