

Interim Reclamation and Stormwater Inspection

Date: 12/06/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 431539

Inspection Document #: 708200749


Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Timbro LC13-77-1HN Pad
Location ID: 431539



Photos 1 & 2. Day tanks at wellheads do not have adequate signage/labels.

Inspection Photos
Location Name: Timbro LC13-77-1HN Pad
Location ID: 431539



Photos 3 & 4. Porta john is not properly anchored and has drifted across the location. Also pictured, trash and debris on location.

Inspection Photos
Location Name: Timbro LC13-77-1HN Pad
Location ID: 431539



Photo 5. Soil stockpile is not marked/signed and does not have adequate stormwater controls measures as the unconsolidated material is susceptible to wind and water erosion in its current state.

Inspection Photos
Location Name: Timbro LC13-77-1HN Pad
Location ID: 431539



Photo 6. Trash and debris observed within the interim areas, east side of production areas.

Inspection Photos
Location Name: Timbro LC13-77-1HN Pad
Location ID: 431539



Photo 7. Trash and debris observed within the interim areas, southwest of the wells.

Inspection Photos
Location Name: Timbro LC13-77-1HN Pad
Location ID: 431539



Photo 8. Western portion of the interim areas. The interim areas appear to be progressing towards Rule 1003 standards with evidence of desirable perennial vegetation observed. A follow-up inspection will be conducted at a future date to ensure vegetative compliance during the active growing season.

Inspection Photos
Location Name: Timbro LC13-77-1HN Pad
Location ID: 431539



Photo 9. Northern interim areas; see comments in Photo 8.