

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2023

Submitted Date:

12/08/2023

Document Number:

708200749

FIELD INSPECTION FORMLoc ID 431539 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431538	WELL	PR	06/01/2021	OW	123-36657	Timbro LC13-76HN	RI
431539	LOCATION	AC			-	Timbro LC13-77-1HN Pad	RI
431540	WELL	TA	02/01/2021	OW	123-36658	Timbro LC13-75HN	RI
431541	WELL	PR	11/01/2020	OW	123-36659	Timbro LC13-76-1HN	RI
431542	WELL	PR	11/01/2020	OW	123-36660	TIMBRO LC13-77-1HN	RI

General Comment:[This is an Interim Reclamation and Stormwater Inspection for Location ID \(431539\).](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Day tank labels at wellheads are not legible (e.g. cracked, peeling, faded). Refer to attached inspection photos.		
Corrective Action:	Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.	Date:	12/06/2023

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	OTHER		
Comment:	Porta-john is not properly anchored and has drifted off into interim areas. Refer to attached inspection photos.		
Corrective Action:	Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607. The location will remain out of compliance until the corrective action has been resolved.	Date:	12/06/2023
Type	TRASH		
Comment:	Trash and debris observed throughout the location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.	Date:	12/06/2023

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>431538</u>	Type:	<u>WELL</u>	API Number:	<u>123-36657</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431539</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431540</u>	Type:	<u>WELL</u>	API Number:	<u>123-36658</u>	Status:	<u>TA</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431541</u>	Type:	<u>WELL</u>	API Number:	<u>123-36659</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>431542</u>	Type:	<u>WELL</u>	API Number:	<u>123-36660</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>

Environmental	
Spill/Remediation:	
Comment:	Remediation Project #30588 is still active and open. Continue to comply with 900 series rules and regulations.
Corrective Action:	<div></div> <div>Date: _____</div>
Emission Control Burner (ECB): _____	
Comment:	<div></div>
Pilot: _____	Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced Pass Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? P

Comment Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas is progressing towards Rule 1003 standards and will need to be re-inspected during the next growing season to verify vegetative compliance; therefore, the location will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action

Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:		
Corrective Action:		Date
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: This location does not comply with Rule 1002.f. During this inspection, a stockpile of soil was observed on the eastern side of the production area; it is unknown if the material is impacted or not, as there were no signs/markers observed. Additionally, there were no temporary control measures around the base of the stockpile and the material is not properly stabilized against wind and water erosion as it is comprised of unconsolidated materials. Additional control measures are needed to contain and stabilize the stockpile. Refer to attached inspection photo.</p>						Date: 12/06/2023
<p>Corrective Action: Comply with Rule 1002.f. The location will remain out of compliance until the corrective action has been resolved.</p>						
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200754	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351226