


Foundation Energy Management  
Lion Government 13-36  
Loc ID: 313252



**Debris still remaining as in previous inspection**



**New debris**

Foundation Energy Management  
Lion Government 13-36  
Loc ID: 313252



New debris



New debris

Foundation Energy Management  
Lion Government 13-36  
Loc ID: 313252



Same debris as in previous inspection



Same debris as in previous inspection

Foundation Energy Management  
Lion Government 13-36  
Loc ID: 313252



**Gap below tank berm has not been resolved**



**Gap below tank berm has not been resolved**

Foundation Energy Management  
Lion Government 13-36  
Loc ID: 313252



Tank battery sign still missing required information as in previous inspection

Same debris as in previous inspection