

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403620385

Date Received:
12/11/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 13 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10421

Name of Operator: PETROLEUM RESOURCE MANAGEMENT CORP

Address: 1110 SOUTH VINE STREET

City: DENVER State: CO Zip: 80210

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Duncan Shepherd

(303) 861-9480

petromgt@comcast.net

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205338

Inspection Date: 10/18/2023

FIR Submit Date: 10/19/2023

FIR Status: _____

Inspected Operator Information:

Company Name: PETROLEUM RESOURCE MANAGEMENT CORP

Company Number: 10421

Address: 1110 SOUTH VINE STREET

City: DENVER State: CO Zip: 80210

LOCATION - Location ID: 436485

Location Name: WPU-36 Number: 1 County: _____

Qtrqtr: Lot 19 Sec: 36 Twp: 11N Range: 89W Meridian: 6

Latitude: 40.860331 Longitude: -107.325012

FACILITY - API Number: 05-081-

-00

Facility ID: 436485

Facility Name: WPU-36

Number: 1

Qtrqtr: Lot 19 Sec: 36 Twp: 11N Range: 89W Meridian: 6

Latitude: 40.860331 Longitude: -107.325012

CORRECTIVE ACTIONS:

9 CA# 185546

Corrective Action: Comply with Rules 419 and 420 regarding annual testing and reporting requirements.
Comply with Rule 434.c inactive well requirements; submit the required Forms and Financial Assurance

Date: 10/18/2023

Response: CA COMPLETED

Date of Completion: 12/02/2023

Operator Comment: Please see Form 17 No. 403608924 for missing 2022 annual Bradenhead Test that was conducted on 11/24/2022. Please see Form 17 No. 403616982 for the 2023 annual Bradenhead Test that was conducted on 12/02/2023 to bring the location into compliance with Rules 419 and 420. Lastly, regarding Rule 434.c., please see Form 5C No. 403601227.

COGCC Decision: _____

COGCC
Representative: _____

11 CA# 185548

Corrective Action: Comply with Rule 1003.a and 603.j

Date: 10/14/2023

Response: CA COMPLETED

Date of Completion: 11/03/2023

Operator Comment: Anchors have been marked per Rule 603.j. All guy line anchors left buried for future use are identified by a marker of bright color 4' in height and not greater than 1' east of the guy line anchor. See attached photo.

COGCC Decision: _____

COGCC
Representative: _____

12 CA# 185549

Corrective Action: Comply with Rule 1003.b and conduct interim reclamation on areas no longer in use including, but not limited to, compaction alleviation (cross-ripping to a minimum depth of 18 inches), recontouring/regrading and revegetation activities. Comply with Rules 1002.f and 1002.c and implement control measures to protect and stabilize the seeded soils. Continue to monitor and manage interim areas to ensure site progresses towards 1003.e.(2) standards.

Date: 10/18/2023

Response: CA COMPLETED

Date of Completion: 12/11/2023

Operator Comment: PRM will submit an interim reclamation variance application for this location in its forthcoming OGDG application as the operator intends to drill additional wells from the existing pad. By 11/03/2023, additional seed was laid around the location perimeter slopes, and coconut mats were laid over the seeded slopes. Please see attached photos.

COGCC Decision: _____

COGCC
Representative: _____

13 CA# 185550

Corrective Action: Comply with Rule 1002.f- Install or repair required stormwater and erosion control measures to minimize erosion, degradation and sediment transport. Ensure BMPs are implemented in accordance with good engineering practices, and maintained in proper functioning condition.

Date: 10/18/2023

Response: CA COMPLETED

Date of Completion: 11/03/2023

Operator Comment: Stormwater erosion control measures were installed or improved to minimize erosion, degradation, and off-site sediment transport. BMPs were installed on the north and east slopes of the pad, and control measures were implemented in the stormwater diversion ditch along the eastern perimeter. Most recent stormwater inspections were performed on 10/24/2023, 11/03/2023, and 11/29/2023. Location where stormwater discharged entered the irrigation ditch was found with no discharge during stormwater inspections after ECMC inspection date. Please see attached photos. If stormwater discharge to the irrigation ditch is observed during any future stormwater inspections, additional BMPs will be installed.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Email with status updates of all other corrective actions will be sent to the contact list noted on the Operator Information tab will be sent by 12/15/2023. Anticipated closure of open corrective actions is following snow melt approximately Q2 2024.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Patrick Lawler

Signed: _____

Title: Environmental Manager

Date: 12/11/2023 2:51:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403621188	Photos
-----------	--------

Total Attach: 1 Files