

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/12/2023

Submitted Date:

12/15/2023

Document Number:

708902538

FIELD INSPECTION FORM
 Loc ID 334780 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456920	Domestic Tap	AC	08/28/2018		-	Domestic Tap 33NESW	AC

General Comment:**CECMC Inspection Report Summary**

On 12/12/2023 at approximately 10:42 hours, I, Compliance Specialist, Wayne Smelser
 Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap 33NESW
 Location # 334780 in Garfield County Colorado.
 While there, I observed the domestic tap is derived from TEP sales line.

This is a summary of inspection report

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Domestic tap - pipe rail fence		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	Domestic tap		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	456920	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following regulator there is an in line odorizer followed by a little Joe regulator. All fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.								
	No PRV observed								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Domestic tap inspection only](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Domestic tap inspection only	smelserw	12/15/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902539	Inspection 708902538 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6358498