

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403612773

Date Received:

12/18/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Butler, Brad

972-345-9195

butleroil@yahoo.com

Sanchez, Chris

chris.sanchez@state.co.us

Bulf, Cathy

cathybulf@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 713600423

Inspection Date: 11/21/2023

FIR Submit Date: 11/28/2023

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 481115

Location Name: Red Rocks

Number: 1-13

County: LAS ANIMAS

Qtrqr: NWN
W

Sec: 1

Twp: 30S

Range: 55W

Meridian: 6

Latitude: 37.465260

Longitude: -103.533560

FACILITY - API Number: 05-071-

-00

Facility ID: 481334

Facility Name: Red Rocks

Number: 1-13

Qtrqr: NWN
W

Sec: 1

Twp: 30S

Range: 55W

Meridian: 6

Latitude: 37.465260

Longitude: -103.533560

CORRECTIVE ACTIONS:

1 CA# 188527

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
Comply with 1002.e. surface disturbance minimization.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/08/2023

BMP's as required per Rule 1002.f.(2)C have been repaired. Loose soils have been stabilized to prevent erosion.

Operator Comment: The landowner requested an existing two track road south across the location be graded. Desert Eagle Operating has reviewed Rule 1002.e. with it's personnel, contractors, and the landowner and they will stay on designated access road boundaries.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 188528

Corrective Action: Comply with Rule 201.a. for safety.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 11/23/2023

Operator Comment: Rule 201.a., to protect and minimize adverse impacts to public health, safety, welfare, the environment, and wildlife resources the open trench was filled with segregated soil at the location.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 188529

Corrective Action: Comply with 1002. b rules for soil removal and segregation.
Comply with 1002.c rules for protection of soils.

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/08/2023

Operator Comment: The open excavation at the wellhead has been remediated. Rocks brought to the surface have been removed. Rule 1002.b. and Rule 1002.c, the topsoil was segregated to the extent possible and soil has been replaced in the open excavation.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 188530

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 11/21/2023

Response: CA COMPLETED

Date of Completion: 12/08/2023

Operator Comment: Per Rule 1002.f.(2), loose soils along the flowline disturbance have been stabilized to prevent erosion.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Desert Eagle Operating endeavors to operate in compliance with all ECMC Rules and Regulations in a manner that protects public health, safety, welfare, the environment and wildlife resources. In compliance with Rule 1002.f.(2)C, the soil along the road has been stabilized to prevent erosion, reference attached photo Access Road Stabilization.pdf. Personnel have been instructed to and will keep vehicles on designated access roads in compliance with Rule 1002.e. The open trench was filled with soil excavated from the trench, rocks were removed, and available topsoil was replaced on the disturbed area, reference photo RR 1-13 Wellhead Area.pdf. The disturbed production areas were tilled and seeded prior to forecasted snowfall to facilitate reclamation.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403627529	Photo of Access Road Stabilization
403627533	RR 1-13 Wellhead Area Trench Remediation

Total Attach: 2 Files