

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate begining to fade and will need to be replaced in the near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:

				corrective date
Type: Ancillary equipment	# 1			
Comment:	electric panel, meter box and transformers			
Corrective Action:		Date:		
Type: Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		
Type: Prime Mover	# 1			
Comment:	electric motor			
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	appears to be plumbed to surface			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239792 Type: WELL API Number: 123-07580 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/15/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 12-20-2023 at approximately 1245 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Form 42 PA Doc #403624901. Operator: KP Kauffman Location name: UPRR 42 Pan Am G Location ID # 333006 Well Name: UPRR 42 Pan Am G 1 API # 05-123-07580 County: Weld Weather: Partly cloudy, clear. Location: Dry. While there, I observed a wellsite, PR at the time of the inspection. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	12/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402658	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6364476