

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2023

Submitted Date:

08/31/2023

Document Number:

694100151

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
405993 _____ Robinson, Taylor _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 72085
Name of Operator: PETRO-CANADA RESOURCES (USA) INC
Address: 5455 BRIGHTON BLVD
City: COMMERCE CITY State: CO Zip: 80022

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
KORENBLAT, MICHAEL		mkorenblat@suncor.com	Principal Agent
kajiwara, JAN	303-297-2100	jan.kajiwara@petro-canada.com	REGULATORY ANALYST

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239628	WELL	PA	09/16/1998	DA	123-07416	HANKINS 1	PA

General Comment:

This is an environmental inspection for Location ID 405993 Hankins #1. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 405993 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: A dead rabbit was found floating in the water which has partially filled the open excavation. KMG has said they will properly dispose of the dead wildlife before they fill the hole.

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Kerr-McGee was asked to re-enter the well. Soil impacts were discovered and subsequently cleaned up. However some impacts remain in situ. The owner/operator of the well is required to submit a Form 19 to the State/ECMC.

Corrective Action: Further clean up of soil impacts will be required by the owner/operator per Rule 912.a. Date: 10/31/2023

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: There is currently an open pit/excavation that KMG is willing to fill until the remaining impacts can be remediated down the road. The Open pit/excavation was filled at the behest of the landowner who needs to plant his field in the next few weeks. A plastic barrier has been placed at the base of pit to delineated where the impacted soil starts.

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
ECMC staff were unable to take a sample at the base of the open pit as it was full of water. A water sample was not able to be procured either due to the dead wildlife in the water. However, staff were able to take PID readings at each of the four side walls, albeit not deep down where the impacts remain due to the water level. For this reason the field screenings all came back negative. The spoil pile was also field screened. KMG was able to take a sample at the base of the open excavation prior to the ECMC's inspection and the results can be found on the ECMC database. KMG is willing to fill the open hole with clean fill dirt and will be doing this in the next couple of weeks as the LO wants to be able to plant his field in that time. A plastic liner will be placed at the bottom of hole to delineate where the impacts begin for aid in future clean up.	robinsotl	08/31/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403551431	INSPECTION SUBMITTED	https://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6275029
694100151	INSPECTION APPROVED	https://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6281807
694100164	photo log	https://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6275014