



00054416

COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 124 - 07067		LEASE NAME: Minkler-Xenia 4-1	
LOCATION: NW/4NE 11-2N-54		OPERATOR: Kingwood? ? Xenia Unit	
DATE: 3-6-97		INSPECTOR: EBB	
Insp. Type: HR	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F
		Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	1" 1) Gas line riser N- #3, 1/4 mile	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	2' above ground	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)	Oil & dirt - misc @ BATTERY site	
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: Restore site, remove riggers
Reseed disturbed area

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

APR 11 6 1997