

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403636107

Date Received:
12/26/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10605
Name of Operator: APEX OIL VENTURES INC
Address: 8823 S. REDWOOD ROAD #D-1
City: WEST JORDAN State: UT Zip: 84088

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Callister, Andrew	(801) 455-8366	andy@qualituoilproperties.com
Katz, Aaron	(970) 765-6300	aaron.katz@state.co.us
Rasmussen, Terry	(801) 487-4721	t.rasmussen@outlook.com
Callister, Jan E	(808) 571-5890	jec-apex@outlook.com
Burger, Craig	(970) 319-4194	craig.burger@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702501767
Inspection Date: 08/22/2023 FIR Submit Date: 08/28/2023 FIR Status:

Inspected Operator Information:

Company Name: APEX OIL VENTURES INC Company Number: 10605
Address: 8823 S. REDWOOD ROAD #D-1
City: WEST JORDAN State: UT Zip: 84088

LOCATION - Location ID: 314354

Location Name: P.R.-TRIGOOD-GOV'T(0365)-61N101W Number: 4NWSE County: RIO BLANCO
Qtrqr: NWSE Sec: 4 Twp: 1N Range: 101W Meridian: 6
Latitude: 40.083442 Longitude: -108.731550

FACILITY - API Number: 05-103-00 Facility ID: 228525

Facility Name: P.R.-TRIGOOD-GOV'T(0365) Number: 10
Qtrqr: NWSE Sec: 4 Twp: 1N Range: 101W Meridian: 6
Latitude: 40.083442 Longitude: -108.731550

CORRECTIVE ACTIONS:

1 CA# 179650

Corrective Action: All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.

Date: 09/05/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator Comment: Wes Goddard reported that debris had been removed

COGCC Decision: _____

COGCC Representative: _____

2 CA# 179651

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 09/10/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator Comment: Wes Goddard, Goddard Construction reported that anchor sites had been marked

COGCC Decision: _____

COGCC Representative: _____

3 CA# 179652

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.

Date: 09/25/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator Comment: This is an "open-hole" completion Totally in the natural fractured Mancos Shale. MIT will not work.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 179653

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 09/10/2023

Response: CA COMPLETED

Date of Completion: 11/15/2023

Operator Comment: No response as to this corrective action

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jan Callister

Signed: _____

Title: Pres

Date: 12/26/2023 2:10:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files