


OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES  
OF THE STATE OF COLORADO

RECEIVED

OCT 3 1980



00054503

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.

COLO. OIL & GAS CONSV. COMM.

5. LEASE DESIGNATION AND SERIAL NO.

L-2595

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

7. UNIT AGREEMENT NAME

-

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR

EXETER EXPLORATION COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 17349, Denver, CO 80217

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

At proposed prod. zone 661' FSL & 1987' FEL (SWSE)

Same

8. FARM OR LEASE NAME

GEBAUER

9. WELL NO.

#1-A

10. FIELD AND POOL, OR WILDCAT

Ruby

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

SWSE, 28, 2N-54W

14. PERMIT NO.

-

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4555'

12. COUNTY

Washington

13. STATE

CO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work

4-7-80 release just date here

This well has been producing from the "D" Sand (4852-55') since January, 1960. Casing problems developed in this well from about 650-1950'. On 3-27-80, a service unit was moved to location. 3/4" rods were found to be parted at 3350' with the 2" tubing full of drilling mud. On 4-3-80 a 4-1/2" Baker mechanical set Model "N" cast iron bridge plug was run on 2" tubing, hydro-tested to 6000# while going into the hole. The BP was set at 4729' (above the "D" Sand). The 2" tubing was pulled and laid down. A dump bailer was run, with 1 sx of cement (approximately 10') dumped on top of the BP.

|     |
|-----|
| DVR |
| FJP |
| HHM |
| JAM |
| JJD |
| RLS |
| CGM |

xc: State of Co. - 10/1/80.

18. I hereby certify that the foregoing is true and correct

SIGNED Walt Pearson

TITLE Manager of Engineering

DATE 8-6-80

(This space for Federal or State office use)

DIRECTOR  
O & G CONSV. COMM.

APPROVED BY [Signature]  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE OCT 24 1980