

State of Colorado
Energy & Carbon Management Commission



Document Number:
403639177

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
12/28/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 5 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10701
Name of Operator: UPLAND EXPLORATION LLC
Address: 424 S MAIN ST
City: BOERNE State: TX Zip: 78006
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Adamczyk, Megan		megan.adamczyk@state.co.us
Rollins, Dustin		dustin@uplandexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504987
Inspection Date: 12/01/2023 FIR Submit Date: 12/01/2023 FIR Status:

Inspected Operator Information:

Company Name: UPLAND EXPLORATION LLC Company Number: 10701
Address: 424 S MAIN ST
City: BOERNE State: TX Zip: 78006

LOCATION - Location ID: 456651

Location Name: Salt Ranch Fee Number: 18 East County:
Qtrqr: SESE Sec: 18 Twp: 11N Range: 64W Meridian: 6
Latitude: 40.914603 Longitude: -104.584484

FACILITY - API Number: 05-123-00 Facility ID: 456651

Facility Name: Salt Ranch Fee Number: 18 East
Qtrqr: SESE Sec: 18 Twp: 11N Range: 64W Meridian: 6
Latitude: 40.914603 Longitude: -104.584484

CORRECTIVE ACTIONS:

1 CA# 188773

Corrective Action: Comply with Rule 427.b. Date: 02/28/2023
It is the responsibility of the Operator to manage all contractors.
Operator shall implement more robust BMPs to ensure speed restrictions are being followed.

Response: CA COMPLETED Date of Completion: 12/21/2023

Upland had previously reduced the lease road speed from 20 mph to 15 mph. Upland is further reducing the

Operator Comment: lease road speed to 10 mph, and is posting new signs. Upland Gate Guard will continue to talk with contactors to ensure they maintain speed below posted speed limit. See attached driving directions that is evidence of what is sent to Upland subcontractors. It has been updated to reflect new posted speed limit. All contractors are provide site specific directions.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 188774

Corrective Action: Comply with the Form 2A Access Road Map (Doc.# 401576196). Failure to comply would be considered a permit violation.

Date: 12/01/2023

It is the responsibility of the Operator to manage all contractors.

The corrective action date is the date the inspection was submitted. Note- the most recent complaints regarding this issue were submitted on 11/15/2023 and 11/27/2023.

Response: CA COMPLETED

Date of Completion: 12/28/2023

Operator Comment: 24 hour Gate Security commenced on 4/24/2023. Upland has a controlled gate and gate security to manage unauthorized access on the lease road. Upland deployed a do not enter sign at the Surface Owner's private residence (photo attached herein) on 4/20/2023. Surface Owner removed the sign. Upland communicates access directions to all contractors. See attached updated directions reflecting new speed limit - this is provided to all contractors.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 188777

Corrective Action: Comply with Notice to Operators: Interim Reclamation Procedures for Delayed Operations (dated January 5, 2017).

Date: 12/01/2023

The corrective action date is the date the inspection was submitted. Note- the complaint regarding this issue was submitted on 11/2/2023.

Response: CA COMPLETED

Date of Completion: 12/28/2023

Operator Comment: Upland Exploration, LLC, has submitted Form 2 renewals 4/27/2023 for additional wells on this location, with the intention of drilling these wells. The currently producing wells began producing in November 2022; the additional wells are proposed to be drilled within 12 months of the current wells being drilled and brought on to production. The original proposed timing for interim reclamation complies with ECMC Rule 1003.b., which allows disturbed areas reasonably needed for subsequent drilling operations to remain disturbed until subsequent drilling operations commence within 12 months. SRF interim reclamation was to commence in November 2023, Upland filed a Form 4 Sundry on May 22,2023 (approved 8/21/2023) requesting extension of interim reclamation based on the refiling of the Form 2 APDs (which have yet to be approved). Given the delay of the approval of Upland's Form 2's, Upland will seek an Interim Reclamation Variance and will bond for the cost in lieu of conducting interim reclamation. Upland is working with counsel to prepare variance hearing application - this should be submitted no later than 1/15/2024 taking into holiday time.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dustin Rollins

Signed: _____

Title: Operations Manager

Date: 12/28/2023 3:03:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403639212

SRF Driving Directions

Total Attach: 1 Files