

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403604399

Date Received:

11/22/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10663  
Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name Phone

Walter, Kyle

Email

kwalter@enduringresources.com

Huntington, Heather

hhuntington@enduringresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 714000030

Inspection Date: 09/28/2023

FIR Submit Date: 10/11/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

### LOCATION - Location ID: 326325

Location Name: W. ANIMAS-WHEELER- Number: 8SWSE County: \_\_\_\_\_  
N34N9W

Qtrqr: SWSE Sec: 8 Twp: 34N Range: 9W Meridian: N

Latitude: 37.216856 Longitude: -107.872419

### FACILITY - API Number: 05-067- -00 Facility ID: 326325

Facility Name: W. ANIMAS-WHEELER- Number: 8SWSE  
N34N9W

Qtrqr: SWSE Sec: 8 Twp: 34N Range: 9W Meridian: N

Latitude: 37.216856 Longitude: -107.872419

### CORRECTIVE ACTIONS:

1 ☒ CA# 183726

Corrective Action: Comply with rule 1003.f and 606.c

Date: 09/28/2023

Response: CA COMPLETED

Date of Completion: 11/21/2023

Operator Comment: WEEDS PULLED AND BROADCAST AND RAKED SEEK ON BARE SPOTS ON THE INTERIM RECLAMATION PHOTOS ATTACHED

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. It has appeared that the gravel pile has been removed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 ☒ CA# 183727

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs per Rule 1002.f. BMP's shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to rule 1004.

Date: 09/28/2023

Response: CA COMPLETED

Date of Completion: 11/21/2023

Operator Comment: BMPS FIXED PHOTOS ATTACHED

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. It has appeared that the gravel pile has been removed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed: \_\_\_\_\_

Title: Permitting Tech

Date: 11/22/2023 9:48:06 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403604399	FIR RESOLUTION SUBMITTED
403604442	CORRECTIVE ACTION PHOTOS

Total Attach: 2 Files