

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403629370

Date Received:  
12/19/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

\*

[rbucogccinspectionreports@chevron.onmicrosoft.com](mailto:rbucogccinspectionreports@chevron.onmicrosoft.com)

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708200741

Inspection Date: 12/06/2023

FIR Submit Date: 12/08/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 430712

Location Name: TIMBRO FEDERAL Number: LD18-74HN County: \_\_\_\_\_

Qtrqr: SWSE Sec: 18 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.744478 Longitude: -103.904172

### FACILITY - API Number: 05-123-00 Facility ID: 430712

Facility Name: TIMBRO FEDERAL Number: LD18-74HN

Qtrqr: SWSE Sec: 18 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.744478 Longitude: -103.904172

### CORRECTIVE ACTIONS:

1 ☒ CA# 189061

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/15/2023

Operator Comment: Complied with Rule 902.b.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
-----------------------	--

2  CA# 189062

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/06/2023

Response: CA COMPLETED

Date of Completion: 12/15/2023

Operator  
Comment:

Complied with Rule 905.e.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
-----------------------	--

## OPERATOR COMMENT AND SUBMITTAL

Comment: Complied with applicable rules on location. Please see attached pictures.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Javier Pellacani

Signed:

Title: HSE

Date: 12/19/2023 9:47:21 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403629370	FIR RESOLUTION SUBMITTED
403629390	Location Photo
403629392	Location Photo

Total Attach: 3 Files