



State of Colorado as Conservation Commission DEPARTMENT OF NATURAL RESOURCES



WELL ABANDONMENT REPORT

This form is to be submitted as an intent whenever a plugging is planned on a borehole. The approved intent shall be valid for one year after the approval date; after that period a new intent will be required. After the plugging is complete, this form shall again be submitted as a subsequent report of the work as actually completed.

ET [] OE [] PR [] ES []

OGCC Operator Number: 94090
Contact Name & Phone: David Walsh
Name of Operator: Walsh Production, Inc.
Address: P. O. Box 30
City: Sterling State: CO Zip: 80751
API Number: 05- 075-6540
Well Name: Henderson Number: #3
Location (QtrQtr, Sec, Twp, Rng, Meridian): NE NW Sec. 18-T9N-R53W
County: Logan Federal, Indian or State lease number: 28044
Field Name: Cedar Creek Field Number: 10400

24 hour notice required, contact @ _____

Complete the Attachment Checklist
Wellbore Diagram
Cement Job Summary
Wireline Job Summary

XX Notice of Intent to Abandon Subsequent Report of Abandonment

Background for Intent Only

Reason for abandonment: [] Dry [X] Production Sub-economic [] Mechanical Problems [] Other
Casing to be pulled: [] No [X] Yes Top of casing cement: 4100'
Fish in hole: [X] No [] Yes If yes, explain details below:
Wellbore has uncemented casing leaks: [X] No [] Yes If yes, explain details below:
Details:

Current and Previously Abandoned Zones

Table with 5 columns: Formation, Perforations, Date, Method of Isolation, Plug Depth. Rows include J Sand and D Sand.

Casing History

Table with 4 columns: Casing String, Size, Cement Top, Stage Cement Top. Rows include Surface and Production casing.

Plugging Procedure for Intent and Subsequent Report

1. CIBP #1 Depth 20 CIBP #2 Depth 4900 CIBP #3 Depth 5050
2. Set 40 SKS cmt from 750 ft. to ...
7. Perforate and squeeze @ ... ft. with ... SKS
8. Perforate and squeeze @ ... ft. with ... SKS
9. Perforate and squeeze @ ... ft. with ... SKS
10. Set 40 SKS 1/2 in 1/2 out surface casing from 180 ft. to 100 ft.
11. Set 10 SKS @ surface
Cut 4 feet below ground level, weld on plate
Dry-Hole Marker [] No [] Yes
Set ... SKS in rate hole Set ... SKS in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing recovered: _____ ft. of _____ in. casing Plugging date: _____
*Wireline contractor: _____
*Cementing contractor: _____
Type of cement and additives used: _____
*Attach job summaries.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.
Print Name David G. Walsh
Signed [Signature] Title: Operator Date: 5-20-97

OGCC Approved: [Signature] Title: SR. PETROLEUM ENGINEER Date: JUN 09 1997
O & G Cons. Comm.

CONDITIONS OF APPROVAL, IF ANY:
NOTIFY ED BINKLEY 48 HRS PRIOR TO PLUGGING. PH NO 970-842-4465