



**KANSAS OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**

☐ NOTICE OF UNSATISFACTORY INSPECTION

☒ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

API No. 05- 075 - 06523

LEASE NAME: Henderson #

LOCATION: SE1/4 18-9N-53

OPERATOR: Walsh

DATE: 5-13-97

INSPECTOR: Ed Brulley

Insp. Type: CA Insp. Status: PA PA: Y N

Pass/Fail: P F Viol.: Y N NOV: Y N

**INSPECTION ITEM**

**COMMENTS**

**INPUT**

<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	work pit	
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)	gravel pump base	
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)	Western Services 750' - 405x, 180' - 405x, 30' - 105x	
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	cultivated	
<b>Miscellaneous</b>		

**CORRECTIVE ACTION REQUIRED:** Remove oil field equipment  
restore to farm use Submit Form 10 - operator

Date Corrective Action Required By: 11-13-97 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.