

NON-HAZARDOUS WASTE MANIFEST

Waste Profile No.

**PAWNEE WASTE**  
LLC

Generator's Name and Mailing Address:

SUMMIT OIL & GAS, LLC  
PO BOX 983038  
PARK CITY, UT 84098

Manifest No.:

**187835**

Bill To Company Name: (if other than the Generator)

Designated Facility Name and Site Address:

Pawnee Waste  
47368 County Rd 118  
Grover, CO 80729

Weld County USR No.

1MJUSR20-15-0048

Facility Phone No.:

(970) 502-7357

Well or Site Name and AFE# / PO / Reference#:

CASTOR 7-59 11-2-5

207310

Truck/Haul Container

Total Quantity

Unit/Wt/Vol

No.:

Type:

5278

Waste Name/Waste Type:

CONTAMINATED OBM

Special Handling Instructions

- Clean Fill
- PCC
- Silt Stone
- After Hours
- Washout
- Cleanout

Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste

Printed/Typed Name:

Signature:

Date:

Derek Dipee

*Derek Dipee*

8-28-23

Transporter Acknowledgement of Receipt of Materials

Transporter Company Name:

Transporter's Phone No.:

Acme

Printed/Typed Name:

Signature:

Date:

Lynn Edwards

*Lynn Edwards*

8-28-23

Discrepancy and Waste Load Rejection Reason: (complete and attach waste rejection form to this manifest)

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above

Printed/Typed Name:

Signature:

Date:

Time In:

Time Out:

G  
e  
n  
e  
r  
a  
t  
o  
r

T  
r  
a  
n  
s  
p  
o  
r  
t  
e  
r

D  
i  
s  
p  
o  
s  
a  
l

F  
a  
c  
i  
l  
i  
t  
y

P drop (ps)  
SSD vel. (ft/min)  
CTR (%)  
CCI