

OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands. File in triplicate for State lands.

RECEIVED

3. LEASE DESIGNATION AND SERIAL NO.

APR 17 1968 4. IF INDIAN LOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

COLO. OIL & GAS CONS. COMM.

1. OIL WELL [X] GAS WELL [] OTHER []



2. NAME OF OPERATOR Edwin J. Bahr & Rosemary Bahr

3. ADDRESS OF OPERATOR 410 Elm Street Sterling, Colo. 80751

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2970' South of North Line 1650' East of West Line

'D' Sand

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4414G1 4423KB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME Huey

9. WELL NO. 1

10. FIELD AND POOL, OR WILDCAT Burr

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

NW-NE-SW Sec. 29-2N-56W

Morgan County Colo.

12. COUNTY OR PARISH 13. STATE

Morgan Colo.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF [] PULL OR ALTER CASING [] FRACTURE TREAT [] MULTIPLE COMPLETE [] SHOOT OR ACIDIZE [] ABANDON [X] REPAIR WELL [] CHANGE PLANS [] (Other) []

WATER SHUT-OFF [] REPAIRING WELL [] FRACTURE TREATMENT [] ALTERING CASING [] SHOOTING OR ACIDIZING [] ABANDONMENT [] (Other) []

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work April 23, 1968 (approximately)

Sand to above perforation then five(5) sacks of cement. Cut off pipe at free point, then run mud to bottom of surface pipe, then run(15) fifteen sacks of cement half in and half out of surface pipe, then mud to 18 (eighteen) feet of top then five (5) sacks of cement to base of celler and weld cap on top of pipe.

Table with 2 columns: Name, Status. Rows: DVR, FJP, HMM, JAM, JJD. Checkmarks are present for FJP, HMM, JAM, and JJD.

18. I hereby certify that the foregoing is true and correct

SIGNED Edwin J. Bahr TITLE Owner DATE April 16, 1968

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE Director DATE APR 23 1968

CONDITIONS OF APPROVAL, IF ANY: